

## ECS Configuration Change Request

Page 1 of

Page(s)

<b>1. Originator</b> Henry Baez	<b>2. Log Date:</b> 10/02/03	<b>3. CCR #:</b> 03-0678	<b>4. Rev:</b> —	<b>5. Tel:</b> 301-925-1025	<b>6. Rm #:</b> 2101D	<b>7. Dept.</b> Sys Eng
<b>8. CCR Title:</b> Replace current 4 256MB DIMM with 8 512MB DIMM in GSFC and LP firewalls.						
<b>9. Originator Signature/Date</b> Henry Baez /s/ 10/02/03			<b>10. Class</b> II	<b>11. Type:</b> CCR	<b>12. Need Date:</b> 10/03/2003	
<b>13. Office Manager Signature/Date</b> Carolyn Whitaker /s/ 10/2/03			<b>14. Category of Change:</b> Initial ECS Baseline Doc.		<b>15. Priority:</b> (If "Emergency" fill in Block 27). Emergency	
<b>16. Documentation/Drawings Impacted</b> (Review and submit checklist):			<b>17. Schedule Impact:</b>		<b>18. CI(s) Affected:</b>	
<b>19. Release Affected by this Change:</b> 6A		<b>20. Date due to Customer:</b>		<b>21. Estimated Cost:</b> None - Under 100K		
<b>22. Source Reference:</b> <input checked="" type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input checked="" type="checkbox"/> Other: CCRs CCR 03-0578 & 03-0579 NCR-37821						
<b>23. Problem: (use additional Sheets if necessary)</b> Both LPDAAC and GDAAC experienced problem with running out of memory and swap space. The firewall did not allow new commands or process to start and required a reset. After reset firewall was functional again. Analyze of logs show that firewall server was running out of memory and using swap. Running in memory is much better.						
<b>24. Proposed Solution: (use additional sheets if necessary)</b> The program has brought 4 GB of memory in the form of 8 512MB DIMM chips for the GSFC and LP DAAC firewall to replace the 1 GB in the form of four 256MB DIMM chips currently install. Currently install four 256MB DIMM will be de-installed and shipped to LaRC and NSIDC to bring those firewalls to 2 GB each.						
<b>25. Alternate Solution: (use additional sheets if necessary)</b> None.						
<b>26. Consequences if Change(s) are not approved: (use additional sheets if necessary)</b> Memory has already shipped and received at GSFC and LP DAAC.						
<b>27. Justification for Emergency (If Block 15 is "Emergency"):</b>						
<b>28. Site(s) Affected:</b> <input type="checkbox"/> EDF <input type="checkbox"/> PVC <input type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input checked="" type="checkbox"/> LaRC <input checked="" type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
<b>29. Board Comments:</b>			<b>30. Work Assigned To:</b>		<b>31. CCR Closed Date:</b>	
<b>32. EDF/SCDV CCB Chair (Sign/Date):</b> Evelyn N. Nakamura /s/ 10/2/03		<b>Disposition:</b> <span style="border: 1px solid red; padding: 2px;">Approved</span> App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS				
<b>33. M&amp;O CCB Chair (Sign/Date):</b>		<b>Disposition:</b> Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS				
<b>34. ECS CCB Chair (Sign/Date):</b>		<b>Disposition:</b> Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS				

## ADDITIONAL SHEET

**CCR #:** 03-0678    **Rev:** — **Originator:** Henry Baez

**Telephone:** 301-925-1025    **Office:** 2101D

**Title of Change:** Replace 4 256MB DIMM with 8 512MB DIMM in GSFC and LP firewalls.

See attached install instructions.

CM01AJA00 Revised 8/2/02

**ECS**